ROTAX. SERVICE INFORMATION

26 UL 94-E

Nov.1994

TBO für ROTAX Motor Type 912 UL Serie

NUR ZUR INFORMATION.
ÄNDERUNGSDIENST NICHT VORGESEHEN.

1) Repeating symbols:

Please, pay attention to the following symbols throughout the service info. emphasizing particular information.

▲ WARNING: Identifies an instruction, which if not followed, may cause serious injury or even

death.

■ ATTENTION: Denotes an instruction which if not followed, may severely damage the engine

or other components.

♦ NOTE: Information useful for better handling.

2) Subject:

Increase of TBO from 600h or 10 years to 1200h or 15 years of operation.

3) Engines affected:

All engines of Series Type 912 UL starting with engine no. 4,152.667.

4) Reason:

In the agreement of the 27. July 1992 with the Type Certificate Authority BAZ the program for the 1. extension of the period between overhauls was conducted. Owing to the good findings of the 5 engines examined the TBO can be increased from the present 600^h / 10 years to the period of 1200^h / 15 years, under consideration of the 600^h inspection.

5) Compliance:

TBO 1200h / 15 years to be effective with engine no. 4,152.667.

6) Remedy:

Not applicable.

7) Accomplishment:

The 600^h inspection to be performed according to instructions overleaf. Revision no. 6 of the Operator's Manual in April 1994 to be entered without delay or the Manual to be exchanged for a new one of ROTAX engine series 912 UL - rev. no. 6.


The necessary measures to be taken by the manufacturer of the engine, ROTAX distributors or their service-centres.

New Operator's Manual with the revision no. 6 from April 1994 entered, is readily available at BOMBARDIER-ROTAX, A-4623 Gunskirchen.

8) Instructions:

On the occasion of the 600^h inspection the following has to be carried out.

8.1) Check of valve spring tension:



ROTAX. SERVICE INFORMATION

26 UL 94-E

Nov.1994

Set cylinder 1 to ignition T.D.C. Fit dial gauge **5** to indicate any movement of valve spring retainer **6**. Fit test lever **7** part no. 877 690 in hollow rocker arm shaft **8** and determine the spring tension on both valves by utilizing a spring balance. Read value on the balance, part no. 877 700, between 0,2 + 0,3 mm (.008 + .012 in.) indication on dial gauge.

♦ NOTE:

Read at first try, with force steadily rising, otherwise action of hydraulic tappet will falsify reading. After a misreading wait until valve is closed again completely. Valve closing can be quickened if necessary, by applying pressure to push rod side of rocker arm with the aid of the test lever.

Check valve springs on all 4 cylinders.

The value shown on the spring balance must not be below 35 N (8 lbf). Valve springs with lower tension must be renewed. Clean sealing face, place both orings on valve cover and attach cover with Allen screw M6 x 30 and washer. Tightening torque 10 Nm (90 in lb).

8.2) Check of float needle:

Detach float chamber by swinging out spring clip.


Examine float valve with float chamber removed. At visible wear of beaded edge at the spring pin the valve has to be renewed. If the distance becomes less than 0,5 mm (see illustration) the float level will be affected too. Check support pin of floats.

At heavy wear of float bracket contact faces, caused by excessive vibration, renew float and float bracket as required.

8.3) Test run:

Connect battery and conduct trial-run including tightness test.

▲ WARNING: Failure to comply with this recommendation could result in engine damage and personal injury!



Translation has been done by best knowledge and judgement - in any case the original text in German language is authoritative