



652 Oliver Street  
Williamsport, PA. 17701 U.S.A.

Tel. 570-323-6181  
Fax. 570-327-7101  
www.lycoming.textron.com

# SERVICE LETTER

Service Letter No. L199  
January 28, 1983

TO: Owners and Operators of Lycoming Reciprocating Aircraft Engines.

SUBJECT: Recommendations Regarding USE OF FUEL

This Service Letter is to clarify Lycoming's position on the fuel grades that are specified for use in our reciprocating engine models.

LYCOMING DOES NOT APPROVE the use of any fuel other than those aviation grades specified in our latest edition of Service Instruction No. 1070.

OUR POSITION IS CLEAR; do not operate your aircraft on any fuel which is not specified.

## NOTE

Lycoming Service Bulletin No. 398 is entitled "Recommendations Regarding Use of Incorrect Fuel". Please refer to this bulletin if your engine has been operated on any fuel that is not specified in Service Instruction No. 1070.